



Oprawy B 100	nt. 8+4+1+6 = 19
— C 200	nt. 6+2 = 8
— C 150	nt. 2+2 = 4
— A 100	nt. 8
— D 100	nt. 1
— F 60	nt. 1
— G 100	nt. 4
— Ex 100	nt. 1
Wgł. 2-bieg. herm.	nt. 2+1 = 3 ✓
Wgł. 1-bieg. herm.	nt. 1 ✓
Wgł. 2-bieg. 10H.	nt. 2 ✓
Pier. herm. schodowy	nt. 2 ✓
Gniazda herm. i bezherm.	nt. 2 ✓
— 24V omph.	nt. 2 ✓
Gniazda silowe 3x16.0	nt. 1 ✓